

C.L. "BUTCH" OTTER - Governor RICHARD M. ARMSTRONG - Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

March 16, 2007

Marcella Heil, Administrator Wildwood Assisted Living 380 1st Avenue East Wendell, ID 83355

License #: RC-836

Dear Ms. Heil:

On February 9, 2007, a life safety code survey was conducted at Wildwood Assisted Living. As a result of that survey, deficient practices were found. The deficiencies were cited at the following level(s):

• Non-core issues, which are described on the Punch List, and for which you have submitted evidence of resolution.

This office is accepting your submitted evidence of resolution.

Should you have questions, please contact Chris Laumann, Health Facility Surveyor, Facility Fire, Life Safety, and Construction Program, at (208) 334-6626.

Sincerely,

Team Leader

Health Facility Surveyor

Facility Fire Safety & Construction Program

CL/sc

c:

Mark Grimes, Supervisor, Facility Fire Safety & Construction Program



C.L. "BUTCH" OTTER, Governor RICHARD M. ARMSTRONG – Director DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-036 PHONE: (208) 334-6036 FAX: (208) 364-1888 E-mail: fsb@idhw.state.id.us

February 16, 2007

Marcella Heil, Administrator Wildwood Assisted Living 380 1st Avenue East Wendell, ID 83355

Dear Ms. Heil:

On February 9, 2007, a life safety code survey was conducted at Wildwood Assisted Living. The facility was found to be providing a safe environment for its residents.

The enclosed form, stating no core issue deficiencies were cited during the survey, is for your records only and need not be returned.

Please bear in mind that non-core issue deficiencies were identified on the punch list, a copy of which was reviewed and left with you during the exit conference. The completed punch list form and accompanying proof of resolution (e.g., receipts, pictures, policy updates, etc.) are to be submitted to this office by March 11, 2007.

Should you have any questions about our visit, please contact me at (208) 334-6626.

Sincerely,

MARK GRIMES

Supervisor

Facility Fire Safety & Construction Program

MG/slc

Enclosure

(X3) DATE SURVEY

Bureau of Facility Standards

STATEMENT OF DEFICIENCIES

(X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION COMPLETED AND PLAN OF CORRECTION IDENTIFICATION NUMBER: 01 - BUILDING 1 A. BUILDING B. WING 13R836 02/09/2007 NAME OF PROVIDER OR SUPPLIER STRÉET ADDRESS, CITY, STATE, ZIP CODE 380 1ST AVENUE EAST WILDWOOD ASSISTED LIVING WENDELL, ID 83355 PROVIDER'S PLAN OF CORRECTION (X4) ID PREFIX SUMMARY STATEMENT OF DEFICIENCIES (X5) COMPLETE DATE (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) R 000 R 000 Initial Comments The facility was found to be in substantial compliance with the fire and life safety requirements of the Rules for Residential or Assisted Living Facilities in Idaho. No core deficiencies were cited during the standard fire/life safety survey conducted on February 9, 2007. The surveyor conducting the survey was: Chris Laumann Health Facility Surveyor Facility Fire safety & Construction Bureau of Facility Standards TITLE (X6) DATE

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM 6IIH21

If continuation sheet 1 of 1



## BUREAU OF FACILITY STANDARDS P.O. Box 83720 Boise, ID 83720-0036 (208) 334-6626 fax: (208) 364-1888

ASSISTED LIVING Non-Core Issues Punch List

-						)
Facility Name			Physical Address	Phone Number		
Administrator			380 15+ Ave E.	28 C 36-SS44		
, I				ŀ		
Survey Team Leader			Wentell, ID	22558		
Survey Team Leader			Survey Type	Survey Date		
Ch	10	<u>uncha</u>	the life safety	2/9/0-	フ	
NON-	-CORE ISSU	ES				
ITEM #	RULE# 16.03.22		DESCRIPTION		DATE RESOLVED	BFS USE
1.	415.00.	Fuel Le Hearing 140	dannentation royld be four	9		
		coctidence the ras to	mairs and got fined water ha	Ac Co		
	***************************************	had been sould with	in the lost sell			100 000 00
				A		55 50 50
)·.	415.05	The Antoniair Fire Extogran, System had not been injected,				
		Excused and tested within the last year			**************************************	
			3			0.00
2	41S.04.	The Fire Alacm Smoke	detection system de helmit be	<u> </u>		
		served and inspected within the last year				APPLICATION
			J			Selection of
4	40.01	No documentation of f	e distracted of the found of the	en line		
		deals through he ment	us of January Moren april, ma	June,	<u> </u>	
		July, august, september				
		),				
		/				
Response Required Date Signature of Facility Representative		Signature of Facility Representative			Date Signed	
3/9	107	1 ///// W. W. S. JA- T to	Al _		102.09	-04